From:

Steve Demczak

To:

Angela Nance; Dennis (WC) 0475 Ware; Suzanne Steab

Date:

7/22/2010 7:58 AM

Subject:

Insp Reports

Attachments: 20100722081302.pdf; 20100722081340.pdf; 20100722081414.pdf; 20100722081442.pdf; 20100722081236.pdf



The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Representatives Present During the Inspection:				
	Dennis Ware			
OGM	Steve Demczak			

Inspection Report

Permit Number:	C0070006
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, June 22, 2010
Start Date/Time:	6/22/2010 10:00:00 AM
End Date/Time:	6/22/2010 12:00:00 PM
Last Inspection:	Wednesday, May 19, 2010

Inspector: Steve Demczak,
Weather: Sunny, 80 deg

InspectionID Report Number: 2407

Types of Operations

Accepted by: jhelfric

6/29/2010

Permitee: PLATEAU MINING CORP
Operator: PLATEAU MINING CORP

Site: STAR POINT MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

Total Permitted	8,885.00
Total Disturbed	87.30
Phase I	95.30
Phase II	95.30
Phase III	8.00

Mineral Ownership

✓	Federal	V	Underground
V	State		Surface
	County		Loadout
V	Fee		Processing
П	Other	П	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issued.

The permittee has pulled out subsidence survey marker throughout the permit area.

Inspector's Signature:

Stephen Went

Date

Thursday, June 24, 2010

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Inspection Type: PARTIAL

Inspection Date: Tuesday, June 22, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale	✓		V	
2.	Signs and Markers	V		V	
3.	Topsoil	✓		<u> </u>	
4.a	Hydrologic Balance: Diversions	V		V	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c		V	П	~	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				П
5.	Explosives			$\overline{\Box}$	
6.	Disposal of Excess Spoil, Fills, Benches				$\overline{\Box}$
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	V		<u> </u>	
9.	Protection of Fish, Wildlife and Related Environmental Issues				$\overline{}$
10.	Slides and Other Damage	V		V	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				一一
13.	Revegetation				
14.	Subsidence Control	✓		<u> </u>	
15.	Cessation of Operations		V		
16.a	Roads: Construction, Maintenance, Surfacing		V		
16.b	Roads: Drainage Controls		V		
17.	Other Transportation Facilities		V		
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other	Π	П		

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Tuesday, June 22, 2010

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The permittee has received Phase II bond release at Starpoint Mine from the Division. The permittee is in the process of getting Phase 3 bonding release on approximately 40 acres for gas drilling by Conoco Philips.

2. Signs and Markers

The identification signs is next to the road to the site.

3. Topsoil

All topsoil was used for reclamation.

4.a Hydrologic Balance: Diversions

Diversions were spot-checked and were functioning as designed.

4.c Hydrologic Balance: Other Sediment Control Measures

The complete site is pocked to prevent sediment from leaving the reclaim area.

8. Noncoal Waste

The site was clear of non-coal waste material.

10. Slides and Other Damage

No slides or other damage were noticed during the inspection.

14. Subsidence Control

The permittee has pulled out subsidence survey marker throughout the permit area. Many of the survey point were found.